



Rhode Island Airport Corporation

December 21, 2022

**ADDENDUM NO. 003
Request for Qualifications No. 33481
Baggage Handling System Improvements
Rhode Island T. F. Green International Airport**

Prospective proposers and all concerned are hereby notified of the following changes in the Request for Qualifications (RFQ) document related to RFQ No. 33481. These changes shall be incorporated in and shall become an integral part of the contract documents.

- 1. What is the expiration of the current contract with Elite Line Services/Daifuku?** *Current contract commenced on 6/14/2019 with a term of five years plus one, two-year extension at sole discretion of RIAC. The first five year term ends 6/13/2024, if RIAC renews the two-year extension, final contract expiration will be 6/13/2026.*
- 2. Identify what modifications will be made under MOU, and timing of the modifications made under the MOU, before/after the assessment and if they will fund modifications twice?** *The Transportation Security Administration (TSA) will be installing automatic tag readers, International Air Transport Association (IATA) scan guns, explosive detection systems (EDS) over height protection devices, and adding new tables and reducing the number of emergency-stops in the search rooms. The timing of these TSA projects are unknown at this time. After the installation, RIAC is responsible for all costs of the operation, maintenance and repairs per the MOU.*
- 3. Copy of maintenance records indicating failure rates, tracking data, list of breakdowns and/or repairs made most often.** *Please see attached (Exhibit A) which lists all corrective, emergency, and breakdown work orders from January 1, 2022 through December 20th, 2022. This list does not include work orders for most v-belt, housekeeping, adding screws, etc.*

####END OF ADDENDUM###

RFQ 33481
EXHIBIT A

Work Order	Description	Equipment	Date Completed	Belt Type
160963	REPAIR LADDER BY ED1/ED2	BHS-N	11/21/2022 13:54	BHS
160960	TEMPORARY REPAIR LADDER ED1/ED2	ED1-LINE	11/18/2022 12:32	BHS
159060	ED1/ED2 LADDER FRABICATED & INSTALLED METAL EDGE TEMPORARY REPAIR	BHS	9/2/2022 15:00	BHS
160948	REPLACED BELT	ED4-03	11/12/2022 2:30	Buffer
160945	REPLACE BELT	ED1-12	11/9/2022 6:55	Buffer
160944	REPLACE BELT	ED1-11	11/9/2022 6:52	Buffer
160943	REPLACE BELT	ED5-17	11/22/2022 5:25	Buffer
160942	REPLACE BELT	ED5-16	11/17/2022 5:27	Buffer
159976	VFD REPLACEMENT	ED6-12	10/11/2022 21:14	Buffer
159117	REDUCER LEAK	ML1-12	9/28/2022 1:04	Buffer
156377	Retrack buffer belt	ED3-03	6/25/2022 11:00	Buffer
161916	REPLACED FAULTY RELAY	CB4-07	12/16/2022 11:30	Buffer
159122	REBUILD MTR AND REINSTALLED TO EQUIPMENT	ML1-12	9/28/2022 23:13	Buffer
157200	replaced tracking belt	ED4-04	7/23/2022 12:02	Buffer
159124	REPLACED SLIP GUARD	CB3-C1	9/30/2022 2:30	Chute
159123	Replaced slip guard	CB3-C1	9/30/2022 0:00	Chute
158075	CHUTE REPAIR	SP3-C2	8/2/2022 5:41	Chute
157199	repaired stabilizing feet	SP3-C1	7/21/2022 19:30	Chute
155293	Damage Reflector	OS2-01DR	5/20/2022 9:30	Door
160937	TROUBLE SHOOT	TC4-02DR	11/3/2022 6:00	Door
154276	ADJUSTMENT ON WEATHER STRIP	TC3-02DR	4/16/2022 16:30	Door
143248	LADDER BEACON LIGHT NOT WORKING	ED1-15	5/30/2022 18:29	Electrical
160969	NO POWER TO ED1 AND ED2	BHS-N	11/27/2022 19:39	Electrical
158646	MSD DISCONNECT CHANGE	ML1-05	8/31/2022 0:40	Electrical
158645	MSD DISCONNECT CHANGE	ML1-04	8/31/2022 0:40	Electrical
160011	REPLACE MSD	TC1-07	10/25/2022 23:28	Electrical
159102	BELT REPAIR	ED8-13	9/21/2022 3:00	Forward Merge
159059	REPLACED MOTOR	ED6-15	9/2/2022 2:30	Forward Merge
159055	ADJUSTED BELT TRACKING	TC6-11	8/28/2022 1:00	Forward Merge
158138	REPLACE BELT	ED8-13	8/29/2022 6:24	Forward Merge
154303	BELT REPLACE	ED4-12	4/21/2022 10:09	Forward Merge
161898	REPLACE BELT	ED8-01SD	12/14/2022 6:50	HSD
161885	REPLACE BELT ON DIVERTER	XO1-01SD	12/6/2022 7:50	HSD
158153	DIVERTER MAKING GRINDING NOISE WHEN CYCLE	ED5-01SD	9/28/2022 17:00	HSD
153264	BELT ADJUSTMENT	SP6-01SD	3/19/2022 14:00	HSD
158158	PADDLE BED MOVEMENT	SP5-01SD	8/27/2022 4:30	HSD
161914	REBUILD PROJECT	CB4-03	12/17/2022 12:00	Powerturn
160941	REPLACE BELT	ML1-06	11/6/2022 8:00	Powerturn
159983	REPLACE BELT	ML1-04	11/3/2022 6:03	Powerturn
159979	CB1-14 PROJECT	CB1-14	11/22/2022 5:29	Powerturn
159958	REPLACE V-BELT	ED2-02	10/3/2022 6:15	Powerturn
159112	REPLACED SCREWS	TC6-02	9/23/2022 20:00	Powerturn
159058	INSTALLED WASHERS IN OUTSIDE RADIUS TO PREVENT FRAME FROM TOUCHING BELT.	TC4-07	8/28/2022 3:00	Powerturn
158161	MISSING SCREWS	TC3-02	8/30/2022 20:58	Powerturn
158156	GEAR BOX LEAK	ML2-02	8/27/2022 3:32	Powerturn
158155	MAJOR OIL GEAR BOX LEAK	ED6-14	9/28/2022 15:30	Powerturn
158098	Repair lacing	ED4-02	8/4/2022 14:00	Powerturn
158078	REPLACE BELT	ED8-02	8/29/2022 6:23	Powerturn
157185	Replace Belt	ED1-02	7/25/2022 7:49	Powerturn
156334	CLEAN EQUIPMENT	CB2-04	6/9/2022 5:00	Powerturn
156333	CLEAN EQUIPMENT	CB2-03	10/1/2022 5:00	Powerturn
156331	CLEAN EQUIPMENT	CB4-04	6/4/2022 16:21	Powerturn
156330	CLEAN EQUIPMENT	CB4-03	6/4/2022 16:20	Powerturn
154217	V-BELTS REPLACEMENT	CB1-11	4/7/2022 13:00	Powerturn
153223	BELT REPLACEMENT	CB3-12	3/10/2022 22:30	Powerturn
137317	HEAD AND TAIL ROLLER REPLACEMENT	CB4-04	5/6/2022 4:03	Powerturn
161894	REPLACE MOTOR BREAKER	ED8-12	12/9/2022 8:30	Powerturn
159116	REDUCER LEAK	ED6-14	9/28/2022 1:02	Powerturn
159980	BELT REPAIR	SP6-03	10/12/2022 5:42	Powerturn
159081	REPLACED V-BELTS	ML2-09	9/8/2022 3:30	Powerturn
157169	REPAIR LACING	ED1-02	7/13/2022 16:00	Powerturn
156386	REPLACES V BELT	CS4-10	6/24/2022 13:06	Powerturn
158157	GEAR BOX LEAK	SP6-01	8/29/2022 8:08	Reverse Merge
158137	MOTOR OVERLOAD ISSUE	SP3-10	9/13/2022 21:33	Reverse Merge
160459	REPLACE DAMAGE PIN	CB1-01	10/26/2022 20:30	Reverse Merge
160460	REPLACED BELT	CB1-01	10/27/2022 13:30	Reverse Merge
152410	MOTOR REPLACEMENT	ED1-01	2/25/2022 14:00	Reverse Merge
161917	BELT TENSION	ED2-01	12/16/2022 13:00	Reverse Merge
161886	REPLACE WHEELS	MU5	12/11/2022 9:01	Sort Pier
160015	REPLACE WHEEL BEARINGS	MU3	10/22/2022 22:00	Sort Pier
159991	PLATES REPLACEMENT	MU3	10/30/2022 17:35	Sort Pier
159056	RELACED SUPPORT WHEELS	MU3	9/1/2022 2:00	Sort Pier
158146	HOUSEKEEPING / CLEANING	MU2	9/28/2022 16:00	Sort Pier
158136	REPLACE WHEEL	MU6	9/13/2022 21:32	Sort Pier
157172	INSTALL MISSING SUPPORT WHEELS	MU3	7/14/2022 20:30	Sort Pier
155289	REPLACE ROLLER	MU5	5/30/2022 8:29	Sort Pier
158924	REPLACE REDUCER AND MTR	MU4	10/10/2022 23:48	Sort Pier
160006	REPLACED GUIDE WHEEL BERRINGS	MU3	10/20/2022 2:30	Sort Pier
159082	Replace broken caster wheels	MU5	9/8/2022 20:30	Sort Pier

RFQ 33481
EXHIBIT A

159973	Cut & laced belt	SP6-04	10/7/2022 19:00	Transport
159108	ADJUSTED &OBSERVED TRACKING	TC2-04	9/23/2022 21:00	Transport
159080	MOTOR REBUILD	ED5-15	9/8/2022 1:21	Transport
158164	BELT TRACKING / CATCH PAN / HOUSEKEEPING	ML4-02	9/17/2022 17:08	Transport
158152	CLEAN OUT DEBRI DRIVE ROLLER	ML1-02	8/30/2022 20:57	Transport
158151	MOTOR OR GEAR BOX MAKING NOISE	CB3-13	8/30/2022 20:49	Transport
158150	WINDING NOISE NON MOTOR	CB3-11	8/26/2022 12:06	Transport
158149	MOTOR REPLACEMENT	ED5-15	8/30/2022 20:49	Transport
158147	REMOVE DUST PACKED ON ROLLERS	SB1-02	9/29/2022 4:58	Transport
158143	GEARBOX GRINDING / BELT SQUEAKING	CB1-13	8/26/2022 22:08	Transport
157170	REPLACE LACING	CB2-05	7/8/2022 11:00	Transport
156373	PROJECT WORK	SP6-02	6/14/2022 10:30	Transport
156372	PROJECT WORK	CB1-13	6/20/2022 12:30	Transport
156332	MOTOR REPLACEMENT	SB2-02	6/10/2022 22:14	Transport
159982	MOTOR SWAP AND REBUILD	TC1-05	10/19/2022 23:39	Transport
159974	replace belt	SP6-04	10/8/2022 8:00	Transport
161904	REPLACED FAULTY PHOTO EYE	TC4-04	12/15/2022 18:30	Transport
161895	Replaced VFD	ED7-14	12/9/2022 13:00	Transport
159118	KNOCKING	ML1-11	9/28/2022 1:07	Transport
154277	MOTOR OVEARLOAD	CB3-02	4/15/2022 10:30	Transport
151443	MOTOR REPLACEMENT	CB3-11	1/7/2022 21:30	Transport
160936	REPAIR MOTOR	ED5-15	11/3/2022 5:29	Transport
159972	REPLACED V-BELTS	CB1-10	10/7/2022 14:00	Transport
159749	REPLACED V-BELT	SP3-03	10/1/2022 0:30	Transport
157212	repair cover drill	TC3-01	7/29/2022 2:00	Transport
151553	BEARING REPLACEMENT	CB3-11	1/27/2022 14:30	Transport
156341	TSA Printer	BHS-S	6/7/2022 18:22	TSA
156340	TSA Printer	BHS-N	6/7/2022 18:19	TSA