

RHODE ISLAND T.F. GREEN INTERNATIONAL AIRPORT (PVD)
FIELD CONDITION REPORT

OFFICE: (401) 691-2265 24 HR: (401) 447-6893

DATE: 9/28/2022

TIME: 21:11

INSPECTED BY: PETER CUSICK

UPDATED BY: PETER CUSICK

WEATHER RELATED UPDATES

SURFACE CONDITIONS

ALL SURFACES DRY

BRAKING ACTION / RwyCC VALUES

RUNWAY TIME TOUCHDOWN MIDPOINT ROLLOUT

TAXIWAY AND APRON BRAKING ACTION : TAXIWAYS: APRONS:

AIRFIELD REMARKS

<u>SURFACES</u>	<u>STATUS</u>	<u>REMARKS</u>
RUNWAY 5-23		AER 05 CENTERLINE MARKINGS OBSCURED BY RUBBER RUNWAY 05: TAXIWAY B EXIT SIGN LEFT SIDE UNLIT
RUNWAY 16-34		CENTERLINE MARKINGS OBSCURED BY RUBBER RUNWAY 16: LOCATION SIGN AT TAXIWAY V/N LEFT SIDE UNLIT RUNWAY 34: LOCATION SIGN AT TAXIWAY M LEFT SIDE UNLIT RUNWAY 34: TAXIWAY V/N EXIT SIGN RIGHT SIDE UNLIT
TAXIWAY A		
TAXIWAY B		DIRECTION / TAXIWAY V DIRECTION SIGN MISSING LOCATION / RUNWAY 16-34 HOLD POSITION SIGN UNLIT
TAXIWAY C		
TAXIWAY C1		
TAXIWAY E		
TAXIWAY F		
TAXIWAY M		
TAXIWAY M1		
TAXIWAY M2		
TAXIWAY N		
TAXIWAY S		
TAXIWAY T		LOCATION / TAXIWAY M DIRECTION SIGN UNLIT RUN UP PAD CLOSED
TAXIWAY V		TAXIWAY CENTERLINE LIGHTS OUT OF SERVICE
NORTHEAST RAMP		
NORTHWEST RAMP		
TERMINAL RAMP		

MISCELLANEOUS AERODROME REMARKS

OBSTRUCTION: CRANE (FLAGGED AND LIT) OPERATING UP TO 110FT AGL .29NM NNW OF AER 23 UNTIL OCTOBER 12TH AT 1700 LCL

RHODE ISLAND T.F. GREEN INTERNATIONAL AIRPORT (PVD)
FIELD CONDITION REPORT

OFFICE: (401) 691-2265 24 HR: (401) 447-6893

DATE: 9/28/2022

TIME: 21:11

INSPECTED BY: PETER CUSICK

UPDATED BY: PETER CUSICK

ALL TAXIWAYS: SURFACE PAINTED MARKINGS NOT STANDARD DUE TO REMOVAL AND PAINTING

UNLIT OBSTRUCTION: RPU ANTENNA UP TO 8FT AGL 256FT NE OF APPROACH END RUNWAY 16 (.51 NNW OF ARP)

ADEQUATE WINGTIP CLEARANCE AVAILABLE (140' OFF CENTERLINE) ON TWY T ADJACENT TO THE RUNUP PAD